

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:				
Company	John Gefferth Permit Coordinator			
Othe	Patrick D. Collins Resident Agent			
Company	Seth McCourt Mine Engineer			
OGM	Jerriann Ernstsen Environmental Scientist II			

Inspection Report

Permit Number:	C0150007			
Inspection Type:	COURTESY			
Inspection Date:	Tuesday, August 24, 2004			
Start Date/Time:	8/24/2004 12:00:00 PM			
End Date/Time:	8/24/2004 3:00:00 PM			
Last Inspection:				

Inspector: Jerriann Ernstsen, Environmental Scientist II

Weather: sunny

InspectionID Report Number: 389

Reprocessing

10/29/2004

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

960.00 Total Permitted

Total Disturbed

Phase I Phase II Phase III

Current Acreages

6.70

Mineral Ownership	Types of Operations		
☐ Federal	Underground		
☐ State	Surface		
☐ County	☐ Loadout		
✓ Fee	Processing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Other

The goal of this visit was to see the previous reclamation efforts.

Inspector's Signature

Jernann Ernstsen, Environmental Scientist II

Thursday, September 02, 2004

Inspector ID Number: 52

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150007 Inspection Type: COURTESY

Inspection Date: Tuesday, August 24, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
- a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.

- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation			V	
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.1	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0150007 Inspection Type: COURTESY

Inspection Date: Tuesday, August 24, 2004

Page 3 of 3

13. Revegetation

There are two major slopes at the mine site that have been reclaimed. I did not evaluate the slope stability or cover. The only comments at this time concerning the site is, the vegetation of the dirt road leading to the mine site is in good-fair condition. The road was supposed to have lower road-cut berm pulled in and regraded. The Permittee did not implement this part of the plan because they planned to redisturb the road to re-reclaim at least one of the slopes. The Permittee gouged and seeded the road. The gouges are still slightly visible. There are shrubs and grasses as well as weeds on the road.